

BUILDING SAFETY CERTIFICATE

Dated: 29.04.2026

No. 1299

It is certified that the existing building Silver Oaks School at Rampura Road Lehra Bega, Distt Bathinda is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2	4				


The building is owned/occupied by Silver Oaks School, Rampura Road Lehra Bega, Distt Bathinda have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Executive Engineer, Public Works Department (B&R) Branch, Bathinda on 23.04.2026 in the presence of Principal, Silver Oaks School, Rampura Road Lehra Bega, Distt Bathinda and that the building/premises is fit for occupancy for running school with effect from 01.04.2026 for a period of 1 Year (Valid till 31.03.2027) in accordance with rule and subject to compliance of the specific conditions as appended.

1. The school must have a plan to handle untoward incidents, including procedures for the safe evacuation of children from the building during an emergency and for coordination with the relevant department. The school should regularly review and update this plan to ensure its effectiveness.
2. If the school requires or has undertaken any additions, alterations, expansions, or modifications to this building, arrangements must be made for an immediate inspection by this office; upon completion of the work, a fresh safety certificate must be obtained from this office.
3. If the building's walls, foundations, or roofs subside due to a natural disaster or any other reason, the school must immediately inform this office about the building's condition, and the building should be put to use only after an inspection has been conducted.
4. Fire safety certificates and electrical safety certificates should be obtained separately from the concerned departments.
5. The school management is responsible for carrying out repairs to the building, keeping its safety paramount. Regardless of this report, the school management remains responsible for the building's safety in all respects.
6. A structural safety certificate valid until 01.04.2026 has been issued by Vikaas Bansal & Associates, and according to their certificate, the school is safe for use during the 2026-27 session; however, since the building was not constructed by this department, the department cannot vouch for the building's structural safety, particularly regarding earthquake resilience.
7. School staff members should be provided with appropriate safety training, including procedures for handling emergencies, first aid, and evacuation protocols.
8. A sum of twenty thousand rupees (₹20,000/-) has been deposited as a building inspection fee, based on the building's covered area, vide GR No. 358269 dated 20.04.2026.
9. This report is not valid for legal purposes.
10. The school's fire safety certificate is valid until 16.04.2029; based on this, the building safety certificate will be considered valid until 31.03.2027.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


Sub Divisional Engineer,
Prov. Sub Division No. 2,
P.W.D. (B&R) Br. Bathinda


Principal
Silver Oaks School
Rampura Road, Bathinda

Signature with Seal: 
Name: Executive Engineer
Designation: Prov. Div. PWD B&R
Bathinda
Name & Address of Department/Office: _____